


# VALVE COVER REPAIR KIT

*Fixes Oil-Contaminated Intake Manifolds*

**Ford Windstar (3.8L) 2003-99**



## PROBLEM

- Check Engine Light
- Engine Misfire
- Lean Diagnostic Trouble Codes

## CAUSES

- Faulty Valve Cover
- Leaking Isolator Bolts
- Oil Contaminated Regulator Vacuum Line
- OE Recognized Problem - Ford TSB - 03-16-1

## DORMAN SOLUTION

- Complete Kit / One SKU
- Multiple Problems / One Easy Fix
- Includes All Parts to Repair the Problem and Prevent Recurring Symptoms
- Almost 1 Million Windstars Manufactured With This Defect